BALDOR · RELIANCE

RPM Insulation Systems Evaluation and Maintenance Guidelines

Installation & Operating Manual

MN434

Any trademarks used in this manual are the property of their respective owners.

Important: Be sure to check <u>www.baldor.com</u> for the latest software, firmware and drivers for your VS1SD product. Also you can download the latest version of this manual in Adobe Acrobat PDF format.

Table of Contents

Section 1 General Information	1-1
Overview	1-1
Safety Notice:	1-1
Section 2 Test Procedures	2-1
Insulation System Resistance Measurement	2-1
Polarization Index Test Procedure	2-1
Report For IEEE429 Dielectric Withstand TEST IN AIR	2-2
Procedure for the Examination and Routine Motor Maintenance	2-2

Section 1

General Information

Overview	This manual contains general procedures that apply to Baldor Motor products. Be sure to read and understand the Safety Notice statements in this manual. For your protection, do not install, operate or attempt to perform maintenance procedures until you understand the Warning and Caution statements. A Warning statement indicates a possible unsafe condition that can cause harm to personnel. A Caution statement indicates a condition that can cause damage to equipment.				
Important:	This instruction manual is not intended to include a comprehensive listing of all details for all procedures required for installation, operation and maintenance. This manual describes general guidelines that apply to most of the motor products shipped by Baldor. If you have a question about a procedure or are uncertain about any detail, Do Not Proceed. Please contact your Baldor District Office for more information or clarification.				
	 Before you install, operate or perform maintenance, become familiar with the following: NEMA Publication MG-2, Safety Standard for Construction and guide for Selection, Installation and Use of Electric Motors and Generators. IEC 34–1 Electrical and IEC72–1 Mechanical specifications ANSI C51.5, the National Electrical Code (NEC) and local codes and practices. 				
Safety Notice:	This equipment contains high voltage! Electrical shock can cause serious or fatal injury. Only qualified personnel should attempt installation, operation and maintenance of electrical equipment. Be sure that you are completely familiar with NEMA publication MG-2, safety standards for construction and guide for selection, installation and use of electric motors and generators, the National Electrical Code, IEC and local codes and practices. Unsafe installation or use can cause conditions that lead to serious or fatal injury. Only qualified personnel should attempt the installation, operation and maintenance of this equipment.				
WARNING:	Do not touch electrical connections before you first ensure that power has been disconnected. Electrical shock can cause serious or fatal injury. Only qualified personnel should attempt the installation, operation and maintenance of this equipment.				
WARNING:	Disconnect all electrical power from the motor windings and accessory devices before disassembling of the motor. Electrical shock can cause serious or fatal injury.				
WARNING:	Be sure the system is properly grounded before applying power. Do not apply AC power before you ensure that all grounding instructions have been followed. Electrical shock can cause serious or fatal injury.				
WARNING:	Avoid extended exposure to machinery with high noise levels. Be sure to wear ear protective devices to reduce harmful effects to your hearing.				
WARNING:	Surface temperatures of motor enclosures may reach temperatures which can cause discomfort or injury to personnel accidentally coming into contact with hot surfaces. When installing, protection should be provided by the user to protect against accidental contact with hot surfaces. Failure to observe this precaution could result in bodily injury.				
WARNING:	This equipment may be connected to other machinery that has rotating parts or parts that are driven by this equipment. Improper use can cause serious or fatal injury. Only qualified personnel should attempt to install operate or maintain this equipment.				
WARNING:	Do not by-pass or disable protective devices or safety guards. Safety features are designed to prevent damage to personnel or equipment. These devices can only provide protection if they remain operative.				
WARNING:	Avoid the use of automatic reset devices if the automatic restarting of equipment can be hazardous to personnel or equipment.				
WARNING:	Incorrect motor rotation direction can cause serious or fatal injury or equipment damage. Be sure to verify motor rotation direction before coupling the load to the motor shaft.				
WARNING:	Be sure the load is properly coupled to the motor shaft before applying power. The shaft key must be fully captive by the load device. Improper coupling can cause harm to personnel or equipment if the load decouples from the shaft during operation				
WARNING:	Use proper care and procedures that are safe during handling, lifting, installing, operating and maintaining operations. Improper methods may cause muscle strain or other harm.				
WARNING:	Incorrect motor rotation direction can cause serious or fatal injury or equipment damage. Be sure to verify motor rotation direction before coupling the load to the motor shaft.				
WARNING:	Motors that are to be used in flammable and/or explosive atmospheres must display the CSA listed logo. Specific service conditions for these motors are defined in NEPA 70 (NEC) Article 500.				
WARNING:	Pacemaker danger – Magnetic and electromagnetic fields in the vicinity of current carrying conductors and permanent magnet motors can result in a serious health hazard to persons with cardiac pacemakers, metal implants, and hearing aids. To avoid risk, stay way from the area surrounding a permanent magnet				
WARNING:	RPM AC permanent magnet motors can induce voltage and current in the motor leads by rotating the motor shaft. Electrical shock can cause serious or fatal injury. Therefore, do not couple the load to the motor shaft until all motor connections have been made. During any maintenance inspections, be sure the motor shaft will not rotate.				
WARNING:	Before performing any motor maintenance procedure, be sure that the equipment connected to the motor shaft cannot cause shaft rotation. If the load can cause shaft rotation, disconnect the load from the motor shaft before maintenance is performed. Unexpected mechanical rotation of the motor parts can cause injury or motor damage.				
WARNING:	Do not use non UL/CSA listed explosion proof motors in the presence of flammable or combustible vapors or dust. These motors are not designed for atmospheric conditions that require explosion proof operation.				
WARNING:	UL Listed motors must only be serviced by UL Approved Authorized Baldor Service Centers if these motors are to be returned to a hazardous and/or explosive atmosphere.				

Safety Notice Continued

WARNING:	Guards must be installed for rotating parts such as couplings, pulleys, external fans, and unused shaft extensions, should be permanently guarded to prevent accidental contact by personnel. Accidental
WARNING:	C-Face motor is intended for mounting auxiliary equipment such as pumps and gears. When mounted horizontally Frames FL, RL and L280C thru L360C, (FDL, RDL and DL180Y-DL220Y) and frames L400D thru L4461D, DL250Y – DL280Y must be supported by the feet and not by the C-Face on D-Flange alone. C-Face motors should be supported by the feet and not by the C-Face. Installations requiring a horizontally mounted motor in frames L280C – L440D, FDL, DL180Y-DL280Y must be supported by the feet as well as C-Face, D- Flange or IEC Flange. Failure to observe these precautions can result in bodily injury and equipment damage.
Warning:	RPM AC permanent magnet motors can induce voltage and current in the motor leads by rotation of the motor shaft even with the motor disconnected from line power. Electrical shock can cause serious or fatal injury. Therefore, do not couple the load to the motor shaft until all motor connections have been made. During any maintenance inspections, be sure the motor shaft will not rotate.
Caution:	Use only a shielded motor power cable with a complete circumferential braided or copper film/tape ground jacket around the power leads. This ground should be secured to the motor frame from within the motor terminal box and must return without interruption to the drive ground. In addition, if the motor and coupled equipment are not on a single common metal base plate, it is important to equalize the equipment ground potentials by bonding the motor frame to the coupled equipment using a high frequency conductor such as a braided strap.
Caution:	Do not over-lubricate motor as this may cause premature bearing failure.
Caution:	Do not lift the motor and its driven load by the motor lifting hardware. The motor lifting hardware is dequate for lifting only the motor. Disconnect the load (gears, pumps, compressors, or other driven equipment) from the motor shaft before lifting the motor.
Caution:	If eye bolts are used for lifting a motor, be sure they are securely tightened. The lifting direction should not exceed a 20° angle from the shank of the eye bolt or lifting lug. Excessive lifting angles can cause damage.
Caution:	To prevent equipment damage, be sure that the electrical service is not capable of delivering more than the maximum motor rated amps listed on the rating plate.
Caution:	If a HI POT test (High Potential Insulation test) must be performed, follow the precautions and procedure in NEMA MG1 and MG2 standards to avoid equipment damage.
Caution:	Do not use an induction oven to heat noise tested bearings. Arcing between the balls and races may damage the bearing. Failure to observe this precaution may result in equipment damage.
Caution:	Do not operate motors with a roller bearing unless a radial load is applied so that damage to the roller bearing does not occur.
Caution:	RPM AC permanent magnet motors with an open enclosure, such as DP–FV, should not be used where ferrous dust or particles may be present. Totally enclosed permanent magnet motors are recommended for these applications.
Caution:	Excessive varnish build can cause motor overheating and damage. Varnish builds up on the winding coil heads and restricts cooling of the coils and end turns. Avoid adding excessive varnish to stator winding.
	If you have any questions or are uncertain about any statement or procedure, or if you require additional information please contact your Baldor District office or an Authorized Baldor Service Center.

Test Procedures

Insulation System Resistance Measurement

A key requirement to achieving proper motor life is the condition of the insulation system. A clean and dry insulation system that is maintained within the thermal limitations according to the insulation class will provide proper motor life. When motors are being used in harsh environments and moisture and contamination are being introduced into the motor winding, it is imperative to perform a maintenance regimen to determine the health of the insulation system and to take steps as necessary to keep the inside of the motor clean and dry. Insulation resistance measurement has been utilized successfully for many years to evaluate the condition of the electrical insulation. Periodic measurements should be taken and records of the results should be kept to analyze the measurement results and to especially determine if a significant decrease in the insulation resistance has occurred. Testing should be performed according to the latest revision of IEEE 43. This document provides detailed guidelines for performing the test and how to analyze the results.

IEEE 43 Recommended Practice for Testing Insulation Resistance of Rotating Machinery.

The insulation resistance measurement is performed by applying a DC voltage to the stator winding and measuring the resistance between the winding and ground. The guidelines for the DC voltage to be applied are:

Rated Motor Voltage	Recommended DC Test Voltage	
<1000	500	
1001 - 2500	500 - 1000	

For insulation in good condition and in a dry state, the insulation resistance will be essentially the same for a test voltage of 500 VDC or 1000 VDC. A significant decrease in the insulation resistance when an increased voltage is applied may be an indication of insulation problems.

The measured insulation resistance of a motor winding will normally increase with the duration of application of the direct test potential. The increase will usually be rapid when the potential is first applied, and the readings gradually approach a fairly constant value as time elapses. The measured insulation resistance of a dry winding in good condition may continue to increase for hours with constant test potential continuously applied; however, a fairly steady value is usually reached in 10 to 15 minutes. If the winding is wet or dirty, the steady value will usually be reached in one or two minutes after the test potential is applied. The slope of the curve is an indication of insulation condition. The polarization index is the ratio of the 10 minute resistance value to the 1 minute resistance value. The polarization index is indicative of the slope of the characteristic curve (resistance on the y axis versus time on the x axis using a $y - \log$ and $x - \log$ scale). The polarization index may be useful in the appraisal of the winding for dryness and for fitness for over-potential test. The 1 minute insulation resistance is useful for evaluating insulation condition where comparisons are to be made with earlier and later data, similarly obtained.

Insulation resistance measurements are affected by several factors including surface condition, moisture, temperature, magnitude of test direct potential, duration of the application of test direct potential and residual charge in the winding.

Insulation resistance of a winding is not directly related to its dielectric strength. It is impossible to specify the value of insulation resistance at which a winding will fail electrically.

If the polarization index is reduced because of dirt or excessive moisture, it can be brought up to proper value by cleaning and drying to remove moisture.

The IEEE recommended minimum value of polarization index for Class B, F and H motors is 2.0.

Polarization Index Test Procedure

- 1. Discharge the winding by grounding the motor power leads.
- 2. It has been proven that when power terminal connection blocks are used this has a significant negative impact on obtaining an accurate insulation resistance measurement. Therefore, it is necessary for the motor power leads to be disconnected from the terminal block before performing the insulation resistance test. The readings must be taken in the same manner each time to be able to compare results.
- 3. The winding temperature must be known.
- Apply voltage to the winding without interruption for 10 minutes. Record the insulation resistance value after voltage has been applied for 1 minute and then at the 10 minute mark. Do not take a measurement at less than 1 minute.
- 5. Insulation test values should be corrected to a common base temperature of 40 °C.

The correction may be made using the Equation: $K_c = K_T R_T$

where

R_c is insulation resistance (in megohms) corrected to 40 °C,

 K_{τ}^{2} is insulation resistance temperature coefficient at temperature T°C (from 6.3.2 or 6.3.3),

R_T is measured insulation resistance (in megohms) at temperature T°C.

For winding temperatures less than the dew point, it is difficult to predict the effect of moisture condensation on the surface. Therefore an attempt to correct to 40 °C for trend analysis would introduce an unacceptable error.

In such cases, it is recommended that the history of the machine tested under similar conditions be the predominant factor in determining suitability for return to service. However, since moisture contamination normally reduces the insulation resistance and/or polarization index readings, it is possible to correct to 40 °C for comparison against the acceptance criteria (see Clause 12).

K_z can also be approximated for insulation resistance halving for a 10 °C rise in winding temperature by application of this next equation.

For example, if the winding temperature at test time was 35 °C, and the insulation was such that the resistance halved for every 10 °C, then the Kt for correction to 40 °C would be derived in the following way: $K_{T} = (0.5)$ or

 $K_{\tau} = (0.5) (40-35)/10 = (0.5) 5/10 = (0.5) 1/2 = 0.707$

The polarization index is the 10 minute reading divided by the 1 minute reading. 6.

7. Discharge the power leads at the conclusion of the test.

An IEEE429 Dielectric Withstand test and report including the polarization index can be provided from the manufacturing plant for new motors in order for the customer to establish a base line value. The test report will include the following information.

REPORT FOR IEEE429 Dielectric Withstand TEST IN AIR

IDENTIFICATION NUM	MBER:	_UNIT:			
TESTER:	DATE:	MOTOR VOLTAGE: _			
INSULATION RESISTANCE CORRECTED TO 40 °C AMBIENT					
AT ONE MINUTE:					
AT TEN MINUTE:					
POLARIZATION INDE	X:				
CERTIFIED BY:					
DATE:					

Procedure for the Examination and Routine Motor Maintenance

- Inspect the motor at regular intervals, approximately every 500 hours of operation or every 3 months. If the 1 environment is abnormally harsh with a potential for excessive contamination, the interval period may need to be less. Keep the motor clean and the ventilation openings clear. If the motor is not properly ventilated, overheating can occur and cause early motor failure.
- Examine exterior of motor for defects, cracks, contamination and any other condition that is different from 2. the condition of the motor as originally shipped. Pay particular attention to grease fittings, grease drains, end rings, and condensate drain holes. Record findings and take pictures. Access motor leads and perform 500 VDC Dielectric Withstand Test. Record readings at 1 minute and 10
- 3. minutes to calculate polarization index.
- 4 Analyze the insulation resistance readings to determine if the motor needs to be removed from service for maintenance. It is recommended to remove the motor from service and perform maintenance on the motor if the 1 minute reading is less than 5 MΩ when corrected to 40 °C or if the polarization index is less than 2.0 or if there is a significant decrease in the values when compared to previous tests.
- 5. If the motor is removed from service for maintenance, measure the shaft extension for total indicator run out and record any damage to the shaft taper that may exist before disassembly of the motor. Record measurements. Take pictures if necessary. Once the motor is disassembled, thoroughly examine all parts of the motor for obvious defects or damage.
- 6 Examine bearings, bearing cavities, shaft bearing journals, seals, bracket drain holes, stator winding, rotor, shaft, motor leads, terminal strip, and stator core. Measure shaft bearing journals and bracket bearing cavities and record measurements.
 - Compare to part drawings. Examine grease for contamination. Record findings and take pictures.
- 7. If the winding and/or core are contaminated, pressure cleaning may be required. Visual inspection and the insulation resistance test results will help determine if cleaning is required.
- If the insulation resistance is low but a visual inspection does not reveal heavy contamination, the culprit may 8. be moisture. If that is the case, the stator core and winding may be dried out by placing the stator in an oven at 250 °F - 275 °F for seven hours.

CAUTION: Excessive varnish build can cause motor overheating and damage. Varnish builds up on the winding coil heads and restricts cooling of the coils and end turns. Avoid adding excessive varnish to stator winding.

- Once the stator has been cleaned and dried, perform a thorough visual examination to look for cracks in 9. the varnish and any possible scratches and nicks on wires. If the examination reveals any cracks, nicks or scratches, adding an overcoat of a thin varnish for repair is acceptable.
- 10. Perform an insulation resistance test on the cleaned, dried, and repaired stator to obtain the 1 minute and 10 minute values to validate the repairs. Record the values for future comparison with values obtained in the field.

Since the motor has been disassembled, the bearings and all seals should be replaced at this time. The brackets and bearing caps should be washed to remove all grease and contamination.

Baldor Sales Offices

UNITED STATES

ARIZONA PHOENIX

4211 S 43RD PLACE PHOENIX, AZ 85040 PHONE: 602-470-0407 FAX: 602-470-0464

ARKANSAS CLARKSVILLE

706 WEST MAIN STREET CLARKSVILLE, AR 72830 PHONE: 479-754-9108 FAX: 479-754-9205

CALIFORNIA

LOS ANGELES 6480 FLOTILLA STREET COMMERCE, CA 90040 PHONE: 323-724-6771 FAX: 323-721-5859

HAYWARD

21056 FORBES STREET HAYWARD, CA 94545 PHONE: 510-785-9900 FAX: 510-785-9910

COLORADO

DENVER 3855 FOREST STREET DENVER, CO 80207 PHONE: 303-623-0127 FAX: 303-595-3772

CONNECTICUT

WALLINGFORD 65 SOUTH TURNPIKE ROAD WALLINGFORD, CT 06492 PHONE: 203-269-1354 FAX: 203-269-5485

FLORIDA

TAMPP/PUERTO RICO/ VIRGIN ISLANDS 3906 EAST 11TH AVENUE TAMPA, FL 33605 PHONE: 813-248-5078 FAX: 813-241-9514

GEORGIA

ATLANTA 62 TECHNOLOGY DRIVE ALPHARETTA, GA 30005 PHONE: 770-772-7000 FAX: 770-772-7200

ILLINOIS

CHICAGO 340 REMINGTON BLVD. BOLINGBROOK, IL 60440 PHONE: 630-296-1400 FAX: 630-226-9420

INDIANA

INDIANAPOLIS 5525 W. MINNESOTA STREET INDIANAPOLIS, IN 46241 PHONE: 317-246-5100 FAX: 317-246-5110

IOWA

DES MOINES 1943 HULL AVENUE DES MOINES, IA 50313 PHONE: 515-263-6929 FAX: 515-263-6515

MARYLAND BALTIMORE 7071A DORSEY RUN RD ELKRIDGE, MD 21075 PHONE: 410-579-2135 FAX: 410-579-2677

MASSACHUSETTS

BOSTON 6 PULLMAN STREET WORCESTER, MA 01606 PHONE: 508-854-0708 FAX: 508-854-0291

MICHIGAN Detroit

DETROIT 5993 PROGRESS DRIVE STERLING HEIGHTS, MI 48312 PHONE: 586-978-9800 FAX: 586-978-9969

MINNESOTA MINNEAPOLIS

13098 GEORGE WEBER DR, SUITE 400 ROGERS, MN 55374 PHONE: 763-428-3633 FAX: 763-428-4551

MISSOURI

ST LOUIS 13678 LAKEFRONT DRIVE EARTH CITY, M0 63045 PHONE: 314-373-3032 FAX: 314-373-3038

KANSAS CITY

1501 BEDFORD AVENUE NORTH KANSAS CITY, MO 64116 PHONE: 816-587-0272 FAX: 816-587-3735

NEW YORK

AUBURN ONE ELLIS DRIVE AUBURN, NY 13021 PHONE: 315-255-3403 FAX: 315-253-9923

NORTH CAROLINA

GREENSBORO 1220 ROTHERWOOD ROAD GREENSBORO, NC 27406 PHONE: 336-272-6104 FAX: 336-273-6628

OHIO

CINCINNATI 2929 CRESCENTVILLE ROAD WEST CHESTER, OH 45069 PHONE: 513-771-2600 FAX: 513-772-2219

OHIO (Continued) CLEVELAND

CLEVELAND 8929 FREEWAY DRIVE MACEDONIA, OH 44056 PHONE: 330-468-4777 FAX: 330-468-4778

OKLAHOMA TULSA

5555 E. 71ST ST., SUITE 9100 TULSA, OK 74136 PHONE: 918-366-9320 FAX: 918-366-9338

OREGON

PORTLAND 12651 SE CAPPS ROAD CLACKAMAS, OR 97015 PHONE: 503-691-9010 FAX: 503-691-9012

PENNSYLVANIA

PHILADELPHIA 1035 THOMAS BUSCH MEMORIAL HIGHWAY PENNSAUKEN, NJ 08110 PHONE: 856-661-1442 FAX: 856-663-6363

PITTSBURGH

159 PROMINENCE DRIVE NEW KENSINGTON, PA 15068 PHONE: 724-889-0092 FAX: 724-889-0094

TENNESSEE

MEMPHIS 4000 WINCHESTER ROAD MEMPHIS, TN 38118 PHONE: 901-365-2020 FAX: 901-365-3914

TEXAS

DALLAS 2920 114TH STREET SUITE 100 GRAND PRAIRIE, TX 75050 PHONE: 214-634-7271 FAX: 214-634-8874

HOUSTON

10355 W. LITTLE YORK ROAD SUITE 300 HOUSTON, TX 77041 PHONE: 281-977-6500 FAX: 281-977-6510

UTAH

SALT LAKE CITY 2230 SOUTH MAIN STREET SALT LAKE CITY, UT 84115 PHONE: 801-832-0127 FAX: 801-832-8911

WISCONSIN

MILWAUKEE 1960 SOUTH CALHOUN ROAD NEW BERLIN, WI 53151 PHONE: 262-784-5940 FAX: 262-784-1215

INTERNATIONAL SALES

FORT SMITH, AR P.O. BOX 2400 FORT SMITH, AR 72902 PHONE: 479-646-4711 FAX: 479-648-5895

CANADA

EDMONTON, ALBERTA 4053-92 STREET EDMONTON, ALBERTA T6E 6R8 PHONE: 780-434-4900 FAX: 780-438-2600

TORONTO

OAKVILLE, ONTARIO 2910 BRIGHTON ROAD OAKVILLE, ONTARIO, CANADA L6H 5S3 PHONE: 905-829-3301 FAX: 905-829-3302

MONTREAL, QUEBEC

5155 J-ARMAND BOMBARDIER SAINT-HUBERT, QUÉBEC CANADA J3Z 1G4 PHONE: 514-933-2711 FAX: 514-933-8639

VANCOUVER,

BRITISH COLUMBIA 1538 KEBET WAY PORT COQUITLAM, BRITISH COLUMBIA V3C 5M5 PHONE 604-421-2822 FAX: 604-421-3113

WINNIPEG, MANITOBA

54 PRINCESS STREET WINNIPEG, MANITOBA R3B 1K2 PHONE: 204-942-5205 FAX: 204-956-4251

MEXICO

LEON, GUANAJUATO KM. 2.0 BLVD. AEROPUERTO LEON, GUANAJUATO, CP37545 MEXICO FAX: +52 477 761 2010





Baldor Electric Company

P.O. Box 2400, Fort Smith, AR 72902-2400 U.S.A., Ph: (1) 479.646.4711, Fax (1) 479.648.5792, International Fax (1) 479.648.5895 www.baldor.com