





CUSTOMER IS RESPONSIBLE FOR DETERMINING THAT BALDOR'S PRODUCT WILL PERFORM SUITABLY IN THE INTENDED APPLICATION.

REV. DESC: REPLACE 36EP3104A83 W/36EP3101B17, 36FH4009A102

REV. LTR: H

VERSION: 02

TDR: 000000949861

FILE: \AAA\00016\779

REVISED: 10:18:18 10/22/2015

BY: ENALEMO

MTL: -



**BALDOR**

HOR 36LC TEFC 182-4 INSTANT REV. W/1" MTO IN BOX (FARM DUTY)

SH 1 of 1